Title: Staticide® Anti-Static Spray for Porous Surfaces

Date: 2/19/09 ml

Following are application guidelines for the Staticide® Anti-Static spray.

Use on Carpeting:

Spray area to be treated with Staticide®. Allow area to dry.

Use on Treadmill Running Belt:

Set the speed of the treadmill to 1.5mph – 2mph. Stand at rear of the treadmill and lightly spray (mist) the treadmill belt as it rotates. 3-4 light sprays (mists) should be enough for a single application. Allow the spray to dry.

L:_Sportsmith Product Support Bulletins\Orginal\ Staticide Anti-Static Spray for Porous Surfaces